

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Charles Reynolds Resident Agent			
OGM	Joe Helfrich Environmental Scientist III			

Inspection Report

Permit Number:	C0070011		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, August 31, 2005		
Start Date/Time:	8/31/2005 1:00:00 PM		
End Date/Time:	8/31/2005 3:00:00 PM		
Last Inspection:	Wednesday, July 27, 2005		

Inspector: Joe Helfrich, Environmental Scientist III

Weather: Sunny 65

InspectionID Report Number: 713

Accepted by: whedberg 9/2/2005

Permitee: **HIAWATHA COAL CO INC**Operator: **HIAWATHA COAL CO INC**

Address: PO BOX 1245, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Site: HIAWATHA MINE COMPLEX

Permit Status: ACTIVE

Current Acreages

Total Permitted	12,177.00	
Total Disturbed	290.00	
Phase I		
Phase II		
Phase III		

Mineral Ownership Types of Operations

•	• •
✓ Federal	✓ Underground
✓ State	Surface
County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hiawatha complex.

Inspector's Signature

ate Thursday, September 01, 2005

Joe Helfrich, Environmental Scientist III
Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 31, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	~		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011
Inspection Type: PARTIAL

Inspection Date: Wednesday, August 31, 2005

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Midterm Review has been completed.

2. Signs and Markers

Signs containing the required information were posted at points of access to the mining facilities.

4.a Hydrologic Balance: Diversions

The portion of the 36" CMP (25) that was damaged has not been repaired to date. Personel and equipment will be brought in from the Bear Canyon facility in October to complete the repairs.